
Tampa International Airport Monthly Noise Monitoring Office Report August 2017







Monthly Noise Report:

- Pilot compliance (corporate and commercial combined) was 99.31%, with 94 total pilot request deviations recorded for the month, out of 13,571 jet operations.
- Remaining deviations not a result of pilot request deviations were due to the west runway being unavailable and/or aircraft that were assigned the east runway by Air Traffic Control.
- Next CNC meetings are scheduled for Thursday, September 21, 2017 from 10:00 a.m. until 11:00 a.m. and from 5:30 p.m. until 6:30 p.m. The CNC meetings were originally scheduled for September 12, however, given the impacts of Hurricane Irma, these meetings were postponed until September 21.


Total Jet Arrivals Runway 10: **1** Total Jet Departures Runway 28: **32**

Top Complaints:

Runway 1R Commercial Jet Arrivals Runway 19L Departures Runway 28 Jet Departures

*Includes: Scheduled runway closures, unscheduled runway closures, aircraft emergencies and wildlife strike inspections.

Airport Map and Notes



-Total Complaints based on complaints logged as of August 31, 2017.

-Commercial jet aircraft are: Boeing, Airbus, McDonald Douglas, Douglas Corporation, Bombardier and Embraer commercial aircraft.

-Pilot Request Deviations includes commercial jet aircraft departures on Runway 19L and commercial jet aircraft arrivals on Runway 1R.

-West Runway Unavailable includes closures for maintenances and emergencies, among other factors.

-This data is compiled from the noise office software provided by Harris Corp. and may differ from official FAA monthly traffic counts.

The Airport operates two primary north-south runways and one east-west runway (Runway 10-28). Arrival and departure directions on those runways are determined by wind direction. Most air traffic utilize the north-south runways. When winds are out of the north, aircraft arrive and takeoff to the north (referred to as a north flow). When winds are out of the south, aircraft arrive and takeoff to the south (referred to as a south flow). Runway 19R and 19L are the runway designations for 'south flow' operations and Runway 1R and 1L are the runway designations for 'north flow' operations.

Runway 1R/19L (the Airport's east runway) is considered noise sensitive.

The Airport does not control aircraft in flight or on the ground. The Federal Aviation Administration has exclusive authority over the movement of aircraft on the ground and throughout the National Airspace System.

Online: www.tampaairport.com/noise-abatement Phone: (813) 870-7843